

GS Elev .:

TC Number: K963-06

Tetra Tech, Inc. 4213 State Street, Suite 100

484.56 ft above MSL

Santa Barbara, CA 93110-2847 VOICE (805) 681-3100 FAX (805) 681-3108 Project: Vandenberg Air Force Base

Log of Well No. 8-MW-20

Location: Approximately 53 feet south of Building 715 southern entrance, and 33 feet from Building 715 south-east corner, SLC-4E.

Date Started: 9/26/02 Completed: 9/26/02 Checked By: David Springer, R.G. # 6962 Logged By: Dave Fenity Ramon Zepeda, BC² Environmental Corp. Drilled By: Drilling Equipment: CME 95 HSA, 6" and 8" I.D. Sampling Equipment: 2-inch I.D. Split Spoon/Encore

> TD: 125 ft bgs TOC Elev.: 484.20 ft above MSL

4" PVC Blank Casing:	from	0	ft bgs to	115	ft bgs
1030.010" Screening Casing:	from	115	ft bgs to	125	ft bgs
Bentonite/Cement Grout:	from	3	ft bgs to	106	ft bgs
Bentonite Transitional Seal:	from	106	ft bgs to	111	ft bgs
Sand Filter Pack:	from	111	ft bgs to	125	ft bgs
TOCKEL 404.00 C. I	1.607				

Page 1 of 6

(ft. bgs)	MATERIAL DESCRIPTION	Material Symbol Material	Well Construction	Sample	per 6" Percent Recovery	PID (ppm) Amb/Smp	REMARKS
5	concrete. Sand, strong brown (7.5YR 4/3), fine grained, roup poorly graded, slightly moist, trace silt, Orcutt S	ınded, S	iP		100	0/0	9/26/02 0835 hrs begin drilling
10				7 8	100	0/0	
15 -				8 10			
20		84 ft btoc \(\subseteq \text{Gro} \)		10		0/0	on: 10/11/02

TETRA TECH, INC.



TC Number: K963-06

Tetra Tech, Inc. 4213 State Street, Suite 100 Santa Barbara, CA 93110-2847 VOICE (805) 681-3100 FAX (805) 681-3108

Project: Vandenberg Air Force Base

Log of Well No. 8-MW-20

Location: Approximately 53 feet south of Building 715 southern entrance and 33 feet from Building 715 south-east corner, SLC-4E.

(ft. bgs)		MATERIAL DESCRIPTION	Material Symbol	Material Type	Cons	Well struction	Sample	Blow Counts per 6"	Percent Recovery	PID (ppm) Amb/Smp	REMAR	RKS
20	_	Sand, strong brown (7.5YR 4/6), fine to medium grained, rounded, medium dense, poorly graded, slightly moist, medium dense, Orcutt Sand.		SP			X	13				
	_											
	_						4					
.5												
	-											
	_											
0		moist, trace silt, medium dense to dense.					X	11 14 20	100	0/0		
	_						4					
	_											
	-											
5												
	_											
	-						4		105	0/0		
0		dark yellowish browm (10YR 4/6), rounded to subrounded, dense, slightly moist.					X	14 17 20	100	0/0		
	_						4					
	_											
	-											
5							1					

TETRA TECH, INC.

Page 2 of 6



Tetra Tech, Inc.

4213 State Street, Suite 100 Santa Barbara, CA 93110-2847 VOICE (805) 681-3100 FAX (805) 681-3108 Project: Vandenberg Air Force Base

Log of Well No. 8-MW-20

Location: Approximately 53 feet south of Building 715 southern entrance, and 33 feet from Building 715 south-east corner, SLC-4E.

Sand, dark yellowish brown (10YR 4/6), fine to medium grained, rounded to subrounded, poorly graded, slightly moist, trace silt. Orcutt Sand. brown (7.5YR 4/4), fine grained, trace silt, trace clay. brown (7.5YR 4/4), fine grained, trace silt, trace clay.	(ft. bgs)	MATERIAL DESCRIPTION	Material Symbol	Material Type	Well Construction	Blow Counts per 6"	Percent Recovery	Amb/Smp	REMARKS
	50 – 60 – 65	Sand, dark yellowish brown (10YR 4/6), fine to medium grained, rounded to subrounded, poorly graded, slightly moist, trace silt. Orcutt Sand. brown (7.5YR 4/4), fine grained, trace silt, trace clay.	Material Symbol	Material Type	Construction Figure 1	14 15 22	100		REMARKS



TC Number: K963-06

Tetra Tech, Inc. 4213 State Street, Suite 100 Santa Barbara, CA 93110-2847 VOICE (805) 681-3100 FAX (805) 681-3108

Project: Vandenberg Air Force Base

Log of Well No. 8-MW-20

Location: Approximately 53 feet south of Building 715 southern entrance and 33 feet from Building 715 south-east corner, SLC-4E.

		and 33 feet from Building 715 south-east corner, SLC							
(ft. bgs)	MATERIAL DESCRIPTION	Material Symbol	Material Type	Well Construction	Sample	Blow Counts per 6"	Percent Recovery	PID (ppm) Amb/Smp	REMARKS
0	Sand, yellowish brown (10YR 5/6), fine grained, rounded, poorly graded, slightly moist, Orcutt Sand.		SP		X	25			
-	rounded, poorly graded, slightly moist, Orcutt Sand.	:							
-	_				4				
-	-				ı				
-	-								
5 -	_				1				
		•							
-	-				d				
	_								
-	-				1				
-	-				4	10	100	0/0.8	
-		. : :				16 21 26	100	0,0.8	
					igstyle igstyle	26			
-	-	`:							
	_	· · · .							
		. : : :			7				
-	-	` : : :							
					4				
	-	. : :							
;		: • •			1				
	}				1				
-	-								
_	.				1				
		:.							
-	-				4				
						14	100	0/0.4	
-	light yellowish brown (10YR 6/4), trace clay.	:::			XI	14 17 23	100	0/0.4	
					\square	23			
-		.::			4				
_									
-	.	``:::			1				
		· : . :							
-		\cdots			4				
5									

TETRA TECH, INC.



Tetra Tech, Inc. 4213 State Street, Suite 100 Santa Barbara, CA 93110-2847 VOICE (805) 681-3100 FAX (805) 681-3108

Project: Vandenberg Air Force Base

Log of Well No. 8-MW-20

Location: Approximately 53 feet south of Building 715 southern entrance and 33 feet from Building 715 south-east corner, SLC-4E.

(ft. bgs)	MATERIAL DESCRIPTION	Material Symbol	Material Type	Wel Constru	l ction	Sample	Blow Counts per 6"	Percent Recovery	PID (ppm) Amb/Smp	REMARKS
95 - - -	Sand, light yellowish brown (10YR 6/4), fine grained, rounded, poorly graded, slightly moist, trace clay, Orcutt Sand.		SP							
00 -							14 19 24	100	0/0.4	
05 —	yellowish brown (10YR 5/6), moist, trace silt.						11 13 17	100	0/2.3	
10 -							9 13	100	0/3.3	9/26/02 0945 hrs collect
_	dark yellowish brown (10YR 4/6), very moist.						18			soil sample V8MWT-110
15 —	dark yellowish brown (10YR 4/4), fine to medium grained, dense, trace clay, moist.				\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		25 50	100	0/5.3	
20						X	26 50 25 50		0/4.8	9/26/02 1000 hours, Collect physical parameters soil sample V8MWTH-120

Page 5 of 6



Tetra Tech, Inc. 4213 State Street, Suite 100 Santa Barbara, CA 93110-2847 VOICE (805) 681-3100 FAX (805) 681-3108

Project: Vandenberg Air Force Base

Log of Well No. 8-MW-20

Location: Approximately 53 feet south of Building 715 southern entrance, and 33 feet from Building 715 south-east corner, SLC-4E.

		<u> </u>							corner, SEC-4E.
Depth (ft. bgs)	MATERIAL DESCRIPTION	Material Symbol	Material Type	Well Constructio	Sample	Blow Counts per 6"	Percent Recovery	PID (ppm) Amb/Smp	REMARKS
120	Sand with silt, dark yellowish brown (10YR 4/4), fine to medium grained, rounded, poorly graded, few silt, trace clay, moist, Orutt Sand.		SP- SM		X	21 50	100	0/2.2	0/07/07
-	well graded, wet.		Ş SW			22 50	100	0/ 10.2	9/26/02 1000 hours, collect soil
105	fat Clay, light yellowish brown (2.5YR 6/3), plastic, stiff, slightly moist to moist.		СН			50 50	100	0/0	sample V8MWT-122 9/26/02
125 — —									1010 hours End drilling total depth 125 ft bgs
-									
130 -	-								
_									
_									
_									
135	-								
_									
_									
140									
140									
_									
145									
TC N	Number: K963-06 TE	TRA I	ЕСН,	INC.					Page 6 of 6